

QUARTERLY REPORT – PUBLIC PAGEGTI PROJECT NUMBER 20754

Validation for Flaw Acceptance of Mechanical Damage to Low Stress Natural Gas Pipelines

DOT Project No.: 257**Contract Number:** DTPH56-08-T-000023**Reporting Period:**1st Project Quarter**Report Issued (Period Ending):**

November 30, 2008

Prepared For:

U. S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Pipeline Safety

Co-Funding Agency

Operations Technology Development, NFP

Prepared By:

Gas Technology Institute
Khalid Farrag, Ph.D., PE
R&D Manager
Khalid.farrag@gastechnology.org
847-768-0803

Gas Technology Institute

1700 S. Mount Prospect Rd.
Des Plaines, Illinois 60018
www.gastechnology.org

Legal Notice

This information was prepared by Gas Technology Institute ("GTI") for DOT/PHMSA (Contract Number: DTPH56-08-T-000023.

Neither GTI, the members of GTI, the Sponsor(s), nor any person acting on behalf of any of them:

- a. Makes any warranty or representation, express or implied with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately-owned rights. Inasmuch as this project is experimental in nature, the technical information, results, or conclusions cannot be predicted. Conclusions and analysis of results by GTI represent GTI's opinion based on inferences from measurements and empirical relationships, which inferences and assumptions are not infallible, and with respect to which competent specialists may differ.*
- b. Assumes any liability with respect to the use of, or for any and all damages resulting from the use of, any information, apparatus, method, or process disclosed in this report; any other use of, or reliance on, this report by any third party is at the third party's sole risk.*
- c. The results within this report relate only to the items tested.*

Project Objectives

The objective of this research is to develop flaw acceptance criteria to provide safe alternative options to the repairs of mechanical damage on gas pipelines operating at stress levels below 40% of the Specified Minimum Yield Strength (SMYS).

The results will provide field protocols and guidelines for use by personnel to decide whether the encountered damage warrants repair or not; thus increasing the safety of the operation at these stress levels and potentially saving costs associated with repairs that are normally applied to highly stressed pipelines (over 40% SMYS).

The proposed research includes performing tests at various damage levels to provide the confidence needed for establishing the repair/no repair criterion. The results will be implemented in a selected model and procedure. The recommendations will be proposed to the appropriate standard development organizations (e.g. ASME, ASTM, etc.) for consideration as an industry standard.

Technical Progress and Results

- Started work on establishing the testing parameters for the validation of the flaw acceptance criteria. The results of the testing program will be used to increase the confidence of the selected model: EPRG Simplified Model.

Since a large number of tests are needed to address the various pipe types and damage sizes, work in this task will optimize the range of pipe and damage characteristics. The testing parameters include pipe diameters from 8 to 16 inches with D/t ratios up to 64. These tests will account for the increased likelihood of re-rounding in larger D/t ratios and thus the development of re-rounding cracks on the larger pipes. These re-rounding cracks, which are not always detected by visual examination, can weaken the strength of the pipe, reducing the effective minimum safe wall thickness and ultimately, causing a pipeline failure.

One of the key parameters that determine the subsequent growth and failure of the pipe during these tests is the pipe's toughness. For this reason, a portion of the test matrix includes low toughness pipe to ensure the model is valid over the whole range of pipe grades.

Most of the previous mechanical damage testing has been based on machined notches applied to the pipe before or after the denting process. This approach allows for good control of the gouge and dent depths but may not capture all of the features of true mechanical damage. In order to capture possible developments of crack during re-rounding, the denting process will be performed on pressurized pipe. A portion of the tests will also be performed using a simulated backhoe to model field conditions.

A meeting with the project consultant (Kiefner & Associates) was performed to discuss initial plan for the testing matrix. The meeting addressed the testing parameters which include the following:

- Pipe grade
 - Pipe size (d/t)
 - Pipe material toughness
 - Damage type (gouge & Dent)
 - Damage size (gouge angle, length, width)
 - Field simulation of backhoe damage
-
- The hydraulic system used to apply damage was modified to accommodate the application of gouges and dents on large size pipes (up to 24 inch diameter).
 - Designed and assembled a new hydraulic system to allow for applying hydrostatic pressure up to 6,000 psig for rupture tests.

Plans for Future Activity

- Complete modifying the mechanical system to apply damage, based on the selected parameters in the test matrix.
- Continue work on establishing the testing parameters based on the previous model verification tests.
- Start the testing program. Apply controlled gouges and dents on the first set of pipes.

Respectfully Submitted,

Khalid Farrag, Ph.D., PE
R&D Manager,
Gas Technology Institute
Khalid.farrag@gastechnology.org
847-768-0803

[End of Report]